## FIELD INSPECTION REPORT

Date of	Inspection: 10	3112020	District: Grays		
Divisio	dy grien i sinterviden a implicació sale galenhanos, proprio proprio con injuito que que				
Name (	of the Road: Ca:		Length (km): A 27 km. yabu to tilaiyo uhund.	gan par par par de primalio en los selegos primar de primar de desgrando por estado a ser esta esta	
	e/Programme:	MAINTENA		and a section of the	
Package No.: Road Id No.:				n er en in maken men er genfanter kriselstat skrivenskat skrivenskat skrivenskat skrivenskat skrivenskat skriv	
	of the Project:	The second secon	pleted/Under Maintenance		
	s a case of:	New Connect	ivity/Up gradation/ Maintenance	la l	
SL No.		Paramet	ers to be checked	Remarks	
1	Pasoment				
a)	Road Junction	na S/U			
b)	Condition of S	NA S/U			
c)	Riding Quality	MW 8/U			
d)	Road Camber			NA S/U	
e)	Whether free aggregates in	NA Yes/No			
f)	Contraction Jo	Na Yes/No			
g)	Compaction o	Yes/No			
2.	Cross Draina	ge	In progress		
2)	Condition of	NIAS/SRI/U			
b)	Condition of	S/SRI/U			
c)	Condition of r	NA S/SRU/U			
3.	Road Furnite	rre:			
a)	Whether sign stones/Pavement	Yes/Nov			
4, -	Compliance !	listory			
a)	Status of ATR	's & any other	s	No	

Overall Rating

Satisfactory	(S)					•
Satisfactory	but	requires	Improver	nent (S	SRI)	
Unsatisfacto	AND REAL PROPERTY.	management or an arrival service of residency were order				

. V.

(Signature)

NAME: Son Kart prosed.

DESIGNATION: E-E