FIELD INSPECTION REPORT

Date of Inspection : 17.12.2020 Division : Bhagalpur		District : Bhagalpur	District: Bhagalpur Length (km): 2.8	
		Length (km) : 2.8		
Name	of Road : Nathnagar Radha Naga	ar Road to Saukhar		
Schem	e/Programme : NEW MAINTEN	ANCE POLICY - 2018		
Package No.: 05 Road Id No.: 20703301009				
Status	of the Project : Ongoing			
Work i	s a case of :		M	
	Paga Paga	Autorité Badallation		
1.	College			
a)	Road Junction condition			
b)	Condition of Surfacing		NA	
c)	Riding Quality		NA	
d)	Road Camber		NA	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		NA	
f)	Contraction Joints provided or not (CC Pavement)		NA	
g)	Compaction of flank/slope & raincuts if any		ΝA	
	Crist Palage			
a)	Condition of head walls in Hume pipe culverts including its painting		NA	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		NA	
c)	Condition of railings/slab/approach for Bridges		NA	
1	Real Finding			
a)	Whether sign board/informatory/cautionary Board/km & 200m stones/Pavement Road marking are provided and Maintained			
•				
a)	Status of ATR's & any others : W	ork has not been started	·	
Overs	ll Rating : Satisfactory (S)		NA	
A 1 619				
Overe	Satisfactory but	requires Improvement (SRI)	NA	

(Signature) (X.)~

NAME: KUMAR RAKESH

DESIGNATION: EXECUTIVE ENGINEER