


FIELD INSPECTION REPORT

| Date of Inspection : 18/12/2020 | | District: Chaya |
|---|--|------------------------------|
| Division : Shergathi | | Length (km): 5.30 km. |
| Name of the Road: GT Road to Bumar | | |
| Scheme/Programme: MAINTENANCE | | New |
| Package No.: | | Road Id No.: |
| Status of the Project: Ongoing/Completed/Under Maintenance | | |
| Work is a case of: New Connectivity/Up gradation/ Maintenance | | |
| Sl. No. | Parameters to be checked | Remarks |
| 1. | Pavement | |
| a) | Road Junction condition | ✓ S/U |
| b) | Condition of Surfacing | ✓ S/U |
| c) | Riding Quality | ✓ S/U |
| d) | Road Camber | ✓ S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | NA Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | NA Yes/No |
| g) | Compaction of flank/slope & raincuts if any | ✓ Yes/No raincuts |
| 2. | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | NA S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | NA S/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | NA S/SRI/U |
| 3. | Road Furniture | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No were in progress |
| 4. | Compliance History | |
| a) | Status of ATR's & any others | No |

Overall Rating :

| | |
|---|---|
| Satisfactory (S) | S |
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |


18/12/2020
(Signature)

NAME: Sri Kant Prasad.

DESIGNATION: E.E.