

FIELD INSPECTION REPORT

Date of Inspection : 17.12.2020		District : Bhagalpur
Division : Bhagalpur		Length (km) : 2.3
Name of Road : Srirampur - Haridaspur		
Scheme/Programme : NEW MAINTENANCE POLICY - 2018		
Package No. : 05		Road Id No.: NEA22000471
Status of the Project : Ongoing		
Work is a case of :		
Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road function condition	NA
b)	Condition of Surfacing	NA
c)	Riding Quality	NA
d)	Road Camber	NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA
f)	Contraction Joints provided or not (CC Pavement)	NA
g)	Compaction of flank/slope & raincuts if any	NA
2	Culverts/Bridges	
a)	Condition of head walls in Hume pipe culverts including its painting	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA
c)	Condition of railings/slab/approach for Bridges	NA
3	Road Markings	
a)	Whether sign board/informatory/cautionary Board/km & 200m stones/Pavement Road marking are provided and Maintained	Yes
4	Compliance Issues	
a)	Status of ATR's & any others : Work Not Started	

Overall Rating :

Satisfactory (S)	NA
Satisfactory but requires Improvement (SRI)	NA
Unsatisfactory (U)	NA

NAME : KUMAR RAKESH

DESIGNATION : EXECUTIVE ENGINEER

(Signature)

17.12.2020