

FIELD INSPECTION REPORT

Date of Inspection :	18/12/2020	District:	Samashipur
Division :	Dalsingh Sarai	Length (km):	3.80
Name of the Road:			
Scheme/Programme:	MAINTENANCE New maint		
Package No.:	Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance completed		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S S/U	
b)	Condition of Surfacing	S S/U	
c)	Riding Quality	S S/U	
d)	Road Camber	S S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	N/A
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N/A
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NA	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	✓

Samir Kumar
(Signature) 18/12/2020

NAME:

SAMIR KUMAR

DESIGNATION:

E.F