FIELD INSPECTION REPORT

	inspection:	19.12.20	District: Lakhifa	now
Division		sonal	Length (km): 0.653' l	
	the Road: P	masy Road		hi Mus
	Programme:	MAINTENANCE	- 3014 VO 2016	10(1700)
Package		- Translation -	Road Id No.:	
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance		
Carlo San San San	a case of:	New Connectivity/Up	gradation/ Maintenance	^
Sl. No.	Parameters to be checked			Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			SAJ
c)	Riding Quality			SAU
d)	Road Camber			-87Ú
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
ſ)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			Testito
a)	Condition of head walls in Hume pipe culverts including its painting St			S/S RI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			-5/SRI/U
c)	Condition of railings/slab/approach for Bridges			€8/SRI/U
3.	Road Furniture			5,5100
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance I	History		
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SAI
Unsatisfactory (U)	SKI

19.1220

(Signature)

NAME:

DESIGNATION: