FIELD INSPECTION REPORT

D		
Date of Inspection:	17/17/2020	District: 140 Kalikan
1310H ;	lanikan	Length (km): 2-400 km
Name of the Road:	701 10	Rahan.
Scheme/Programme:	MAINTENANC	CE
Package No.: BR.	16R-152	Road Id No.:
Status of the Project:	Ongoing/Compl	eted/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

	Parameters to be checked	Remarks	
Sl. No.	the same of the sa		
l.	Pavement	od I	
a)	Road Junction condition	SAU	
b)	Condition of Surfacing	\8 /U	
c)	Riding Quality		
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Pamalanda Lom

DESIGNATION: JE