FIELD INSPECTION REPORT

FIELD INSPEC	TION ROLL	
	District: Kallham	
The same of the sa	A STATE OF THE PROPERTY OF THE	
	The same of the sa	
120 01	Road Id No.:	
Dogoing/Completed	/Under Maintenance	
New Connectivity/U	p gradation/ Maintenance	months of the
Parameters to	be checked	Remarks
condition		S/U
-		√ 8/TU
		√8/ U
		√S/ U
from defects such	as visible cracks, exposed	Yos/No
		Yés/No
f flank/slope & raincu	ts if any	Yes/No
ge di		
ead walls in Hume pi	pe culverts including its painting	√8/SRI/U
butment & Wing wal	ls, Slab in RCC culverts	S/SRI/U
ilings/slab/approach	for Bridges	S/SRI/U
œ.		
boards/informatory/ont road markings are	cautionary Board/km & 200m provided and maintained	Yes/No
istory		
s & any others	William Committee of the Committee of th	Ash San Ash San
	MAINTENANCE MAINTENANCE New Connectivity/L Parameters to condition Surfacing from defects such case of CC Pavement. ints provided or not (of flank/slope & raincurge ead walls in Hume pip. butment & Wing wallings/slab/approach re boards/informatory/ont road markings are istory	Length (km): 1.136 km TD2 To Hor por a MAINTENANCE Leq. 951 Road Id No.: Ongoing Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance Parameters to be checked condition Gurfacing from defects such as visible cracks, exposed ease of CC Pavement. ints provided or not (CC Pavement) flank/slope & raincuts if any ge ead walls in Hume pipe culverts including its painting butment & Wing walls, Slab in RCC culverts tillings/slab/approach for Bridges re boards/informatory/cautionary Board/km & 200m int road markings are provided and maintained istory

Overall Rating

Satisfactory (S)	2
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Kamahandsa Kom

DESIGNATION: 15

(Signature)

Scanned by CamScanner