

FIELD INSPECTION REPORT

(MAGSY GEN)

Date of Inspection :	17-12-2020	District:	Rishangang
Division :	RWD, Kishangang-2	Length (km):	1.100 KM
Name of the Road:	PWD Road to Banshari		
Scheme/Programme:	MAINTENANCE ✓		
Package No.:		Road Id No.:	212059/2015
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S/U	
a)	Road Junction condition	S/U ✓	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Gross Drainage	S/SRI/U	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture	Yes/No	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History	No.	
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

17/12/20
(Signature) JE

NAME: Jnanesh Kumar Tripathi
JE, Thakurganj.