FIELD INSPECTION REPORT

		ECTION REPORT	<u> </u>
Date of Inspection:	18112/2020	District: Argrica	
Division: Port	sesgeni	Length (km): 2.736 k	
Name of the Road:	Kirkhichya to	enouhan tola.	
Scheme/Programme:	MAINTENANCE		12
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Complete	led/Under Maintenance //Up gradation/ Maintenance	The second secon
Work is a case of:	Newtoonneedivity	in in a proton to the state of	
1 Davement			S/U
a) Road Junction	condition		S/Ú
	Condition of Surfacing		
7.11 0 1:41			
d) Road Camber	Road Camber Whether free from defects such as visible cracks, exposed		
c) aggregates in c	ase of co raidmin		Yes/No
f) Contraction Joi	nts provided or not	(CC Pavement)	Yes/No.
g) Compaction of	flank/slope & rainc	uts ir any	
Gross Dealnag		in sulverts including its painting	S/SRI/U
a) Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
Condition of head water Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Condition of railings/slab/approach			š/srl/U
c) Condition of rai	lings/slab/approacn	Iot phogos	
Section 1	oards/informatory/	Roard/km & 200m	Yes/No
) Whether sign contents stones/Pavement	road markings are	provided and maintained	
(complete de la			NO
Status of ATR's	& any others	1	. •

Overall Rating

Satisfactory (S)	SRI
Satisfactory (S) Satisfactory but requires Improvement (SRI)	3.
Unsatisfactory (U)	

(Signature)

day

NAME: