

FIELD INSPECTION REPORT

Date of Inspection : 18/12/2020		District: Aramda	
Division : Forbengau		Length (km): 2.498 Km	
Name of the Road: Kinkhya manar to adwasi tola.			
Scheme/Programme: MAINTENANCE		Road Id No.:	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
STATUS			
Pavement		S/U	
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	Yes/No	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
GROSS DAMAGE			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRU/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRU/U	
c)	Condition of railings/slab/approach for Bridges	S/SRU/U	
ROAD FURNITURE			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
COMPLIANCE HISTORY			
a)	Status of ATR's & any others	NB	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

Alka
75

NAME: