


FIELD INSPECTION REPORT

Date of Inspection : 18/12/2020.		District : GAYA	
Division : Neemchak Bathani ; Sub Division - Manpur.		Length (Km.) : 0.576	
Scheme/Programme: PMGSY	MAINTENANCE	L061 Manpur Bhojra Sanagato Road T02 to Nanhak chak (ODR-61.)	
Package No. : BR-12R-760		Road Id No. :	
Status of the Project : Under Maintenance	Ongoing/Completed/Under Maintenance		
Work is a case of : Maintenance	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1 Pavement			
a)	Road Junction condition	U	S/U
b)	Condition of Surfacing	S	S/U
c)	Riding Quality	S	S/U
d)	Road Camber	S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A	Yes/No
g)	Compaction of flank/slope & raincuts if any	No.	Yes/No
2 Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	N/A	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A	S/SRI/U
3 Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	yes.	Yes/No
4 Compliance History			
a)	Status of ATR's & any others.	NO ATR	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—


18/12/2020.