FIELD, INSPECTION REPORT

Date of Inspection: 17/1420			District: JEHANABAD
Division: Ring IN. Toheraball.			Length (km): 0.719 KM
Name	of the Road: Lo72 Sho	skusabad. Kistha Haoruman	r-Hardisto Madayan purgo
Name of the Road: Lo72 Shakusabaq. Kistka Haruman Scheme/Programme: Maintim			NAME OF TAXABLE PARTY OF TAXABLE PARTY OF TAXABLE PARTY OF TAXABLE PARTY.
Package No:			Road Id No.:
Status of the Project:		Ongoing/Completed/Under gradation/Maintenance	
Work is a case of:		New Connectivity/Up gradation/Maintenance	
S.N	Paramet	ers to be checked	Remarks
1	Payment		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		8/10
c)	Riding Quality		S/U
d)	Road Camber		S/U_
e)	Whether free from defects such as visible cracks, exposed Yes/No		
	aggregates in case of CC	Pavement.	
f)	Contraction joints provide	led or not (CC Pavement)	Yes/No
(g)	Compaction of flank/slo	pe & raincuts if any	Yes/No
2.	Cross Drainage		
a)			S/SRI/U MAA
	its painting		
b)			S/SRI/U HIA
	culverts.		
c)			S/SRI/U X/A
3.	Road Furniture	The state of the s	
a)	Whether sign boards/informatory/cautionary Board/km &		Yes/No
		road markings are provided and	
227712281120N	maintained		
4.	Compliance History	The state of the s	
a)	Status of ATR's & any others		MC.

Overall Rating:

Satisfactory (S)	9
Satisfactory but requires	
Improvement (SRI)	
Unsatisfactory (U)	

J. Signalling 20

NAME: 19D. SHOALB ALAM.
DESIGNATION: J.E. RWD. Rondy Jes

1