## FIELD INSPECTION REPORT

	Inspection:	19.12.20	District: Land hi son	ey'
Division	wien	ifanoi"	Length (km): 0.82K	M
	f the Road:	-101-Tolh	The state of the s	
	Programme:	MAINTENANCE		
Package		and the state of t	Road Id No.:	
			ed/Under Maintenance	
Work is	a case of:	New Connectivity	Up gradation/ Maintenance	
Sl. No.		Parameters t	o be checked	Remarks
1.	Pavement			
a)	Road Junction condition			SAU
b)	Condition of Surfacing			SH
c)	Riding Quality			SA
d)	Road Camber			48/10
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
I)	Contraction Joints provided or not (CC Pavement)			¥es/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			<del>-s/</del> srl/u
c) .	Condition of railings/slab/approach for Bridges			<del>S</del> /SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			¥es/No
4.	Compliance H	listory		St. Stant -

Overall Rating

Status of ATR's & any others

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SAI
Unsatisfactory (U)	-

19.12.20

(Signature)

70

NAME:

**DESIGNATION:**