


# FIELD INSPECTION REPORT

|                                                                                   |                            |
|-----------------------------------------------------------------------------------|----------------------------|
| Date of Inspection : 18-12-2020                                                   | District: Jamui            |
| Division : Jharkhand                                                              | Length (km): 0.760         |
| Name of the Road: <del>to</del> L127. Pipera bank Akhooiya DMGSY road to Khasidli | Mandal Tdo.                |
| Scheme/Programme: MAINTENANCE                                                     | PMGSY                      |
| Package No.: BRIS R - 376                                                         | Road Id No.: - 20804202210 |
| Status of the Project: Ongoing/Completed/Under Maintenance                        | ✓                          |
| Work is a case of: New Connectivity/Up gradation/ Maintenance                     | ✓                          |

| Sl. No. | Parameters to be checked                                                                                             | Remarks    |
|---------|----------------------------------------------------------------------------------------------------------------------|------------|
| 1.      | Pavement                                                                                                             |            |
| a)      | Road Junction condition                                                                                              | ✓S/U       |
| b)      | Condition of Surfacing                                                                                               | ✓S/U       |
| c)      | Riding Quality                                                                                                       | ✓S/U       |
| d)      | Road Camber                                                                                                          | ✓S/U       |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | ✓Yes/No    |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | ✓Yes/No    |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No ✓   |
| 2.      | Cross Drainage                                                                                                       |            |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓S/SRI/U   |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U NA |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U NA |
| 3.      | Road Furniture                                                                                                       |            |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No ✓   |
| 4.      | Compliance History                                                                                                   |            |
| a)      | Status of ATR's & any others                                                                                         | NO         |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            | -   |
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory (U)                          | -   |

  
 18-12-2020  
 JE  
 (Signature)

NAME: Kabilekh Kumar

DESIGNATION: Junior Engineer