FIELD INSPECTION REPORT

	FIELD INGIECTION RELOAD	
Date of I	Inspection: 16-12-2020 District: Kadika	~ :
DIVISION	l angth (km):	
Name of	The Road: Too To Police Control	
Scheme/	Programme: MAINTENANCE	
Package	No.: Be-168-312 Road Id No.:	
Status o	f the Project: Ongoing Completed/Under Majatenance	
Work is	a case of: New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	√8/U
b)	Condition of Surfacing	√S/U
c)	Riding Quality	√8/TU
d)	Road Camber	√8/TU
e)	Whether free from defects such as visible cracks, exaggregates in case of CC Pavement.	105/140
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its pa	ninting S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	√8/SRI/U
c)	Condition of railings/slab/approach for Bridges	√8/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No
4.	Compliance History	
ACCUSED TO SECURE OF THE PARTY		ł

Overall Rating

Satisfactory (S)	\$
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Ranchandse Kann

Status of ATR's & any others

DESIGNATION: JE