

# FIELD INSPECTION REPORT

Date of Inspection : 11-12-2020	District: GOPALGANJ
Division : Works division, Gopalganj-2	Length (km): 2.00 KM
Name of the Road: Pipra Manga To Mathiya to Buchiya PMGSY Road.	
Scheme/Programme: MAINTENANCE	GTNSY
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	✓
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

ROAD SURFACE DAMAGED DUE FLOOD.  
(HEAVY WATER ON <sup>WHOLE</sup> ROAD SURFACE).

*Sawit*  
11/12/2020  
(Signature)

NAME: SAMIT SINGH

DESIGNATION: JUNIOR ENGG