## FIELD INSPECTION REPORT

	Inspection :	19.12.20	District: Lase his for	ai _
Division	: Late hi	Sareie	Length (km): 0.79 Km	
	the Road:	Lozz to Ro		
	Programme:	MAINTENANC	E	
Package			Road Id No.:	
	f the Project:		eted/Under Maintenance \	
1781 AND 41	a case of:	New Connectivit	y/Up gradation/ Maintenance —	
Sl. No.		Parameters	to be checked	Remarks
1.	Pavement			
a)	Road Junction	condition		us/ti
b)	Condition of S	Surfacing		S/U·
c)	Riding Quality	Riding Quality		S/U·
d)	Road Camber			<b>-8/U</b>
c)	Whether free aggregates in	e from defects s case of CC Paveme	such as visible cracks, exposed ent.	¥es/No
(J)	Contraction Jo	oints provided or no	ot (CC Pavement)	Yes/No
g)	Compaction o	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Draina	ge		
a)	Condition of la	nead walls in Hume	pipe culverts including its painting	₩S/SRI/U
b)	Condition of A	Abutment & Wing	walls, Slab in RCC culverts	-8/SRI/U
c)	Condition of r	Condition of railings/slab/approach for Bridges S7S		S7SRI∕U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No	
4.	Compliance I	listory		
a)	Status of ATR	's & any others		

Overall Rating

Satisfactory (S)	SAI
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

19.12.200 JE (Signature)

NAME:

DESIGNATION: