

FIELD INSPECTION REPORT

Date of Inspection : 18-12-2020		District: Lakhisarai	
Division : Lakhisarai		Length (km): 0.750	
Name of the Road: Adarsh Laxmi pur pm 657 road to Teli tola Baraitole primary School Adarsh Laxmi pur -			
Scheme/Programme: MAINTENANCE		Road Id No.:	
Package No.:		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	S
b)	Condition of Surfacing	S/U	S
c)	Riding Quality	S/U	S
d)	Road Camber	S/U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No	Yes
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	H.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	H.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	H.A.
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Yes
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

~~Road is under ATR~~

18.12.2020
AE Barahiya
(Signature)

NAME: