## FIELD INSPECTION REPORT

Date o	f Inspection:	19 12 2020 Distr	ict: kishangangi	
Divisio	The same of the sa		th(km): 1.00 km	
Name	of the Road:	Kamplour Mus	lin Tola to Toy	
Schem	e/Programme:	GTANY	(1) (8)	
Packag	e No.:		oad Id No.:	
Status of the Project: Ongoing/Completed /Under Maintenance /			Jnder Maintenance	
Work is a case of: New Connectivity/ Up gradation / Maintenance				
S1. No	Parameters to be checked			Remarks
1.	Pavement			V S/U
a)	Road Junction Condition			1 S/U
b)	Condition of Surfacing			I_S/U
c)	Riding Quality			₩ S/U
d)	Road Camber			₩ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints Provided or not ( CC Pavement)			₩es/No
g)	Compaction of flank / shop & raincuts if any			Yes/Np
2.	Cross Drainage			100,110
a)	Condition of head walls in Hume pipe culverts including its Painting			₩S/SRI/U
b)	Condition of Abutment & Wing walls slab in RCC culverts			「S/SRI/U
c)	Condition of railings/Slab/approach for Bridges			S/SRI/U
3.	Road Furniture			L 3/3/11/0
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			✓Yes/No
4.	Compliance His			
a)	Status of ATR's	& any others	and the second second	No ATR

## Overall Rating:

	-0-
1	_
-	
	,

NAME: Ex. AMAL PRAKASH

(Signature)