

FIELD INSPECTION REPORT

Date of Inspection: 15/12/20		District: Kishanganj
Division: KNE 2		Length (km): 1.40 Km
Name of the Road: L036 TO G99/RX T019		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 21205901800
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4. Compliance History		
a)	Status of ATR's & any others	

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	SRI
	Unsatisfactory (U)	

(Signature) 15/12

NAME: B. Mandal
DESIGNATION: SE