## FIELD INSPECTION REPORT

Date o	f Inspection:	9 12 2020	District: Kish - ha ani	
Divisio	of the Road:		Length(km): 1.350 km	
Name	of the Road: N	ajarpur 1	10 L046	
Schem	e/Programme:	GINY		
Packag	e No.:		Road Id No.:	
Status	of the Project:	Ongoing/Comp	pleted /Under Maintenance	
Work is	s a case of:	New Connectiv	vity/ Up gradation / Maintenance	
\$1. No	Parameters to be checked			Remarks
1.	Pavement			V S/U
a)	Road Junction Condition			LS/U
b)	Condition of Surfacing			VS/U
c)	Riding Quality			₩ S/U
d)	Road Camber			V 5/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints Provided or not (CC Pavement)			Yes/No
g)	Compaction of flank / shop & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its Painting			₩5/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts			S/SRI/U
c)	Condition of railings/Slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			✓Yes/No
4.	Compliance History			
a)	Status of ATR's 8	any others		NO ATH

## Overall Rating:

Satisfactory(S)	-9-
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

(Signature)

NAME: FO AMAL PRAKASH