FIELD INSPECTION REPORT

Date of	Inspection . 1	T LO O AD A Disa	wints no II i	
Date of Inspection: 18.12.2020 Division: Than the arriver:			District: Madhybani	
Sild of file better				
Name of	the Road: Ro		havi path to Nav	lakha
Scheme/Programme: MAINTENANCE				
Package		MMUSY Roa		
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance		
THE PERSON NAMED IN	a case of:	New Connectivity/Up grad	dation/ Maintenance	
Sl. No.		Parameters to be checked		Remarks
1.	Pavement	开发的一种,我们就是一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个		
a)	Road Junction condition		S/U	
b)	Condition of Surfacing		√s/U	
c)	Riding Quality		√S/U	
d)	Road Camber .		S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Ýes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U

Whether sign boards/informatory/cautionary Board/km & 200m

stones/Pavement road markings are provided and maintained

Overall Rating

3.

a)

4.

a)

Satisfactory but requires Improvement (SRI)		
	SRI	
The state of the s	provement (SRI)	

(Signature)

Yes/No

NAME: Dhananjay kyona

Road Furniture

Compliance History

Status of ATR's & any others

DESIGNATION: