FIELD INSPECTION REPORT

	nspection:	19-12-20	District: Laktor	• :
Division :	Laketi	Sarai	Length (km):	
	the Road: S	herma Nam	forme Road to f	
		MAINTENANCE	Tours Rosa in T	ac gara,
Package		10 10	Road Id No.:	- W
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance		
The Company	case of:	New Connectivity/	Up gradation/ Maintenance	
Sl. No.	Parameters to be checked			Remarks
1.	Pavement			
a)	Road Junction condition			∪S/U
b)	Condition of Surfacing			SAU
c)	Riding Quality	-		
d)	Road Camber			S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
I)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			0
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	e
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

19.12.20 JE

(Signature)

NAME:

DESIGNATION: