

FIELD INSPECTION REPORT

Date of Inspection: 18/11/20		District: JEHANABAD
Division: RWD (M) DDA, Jehanabad		Length (km): 1.95 KM
Name of the Road: L137 Dhanabhai to Mussonda		
Scheme/Programme:		MAINTENANCE ✓
Package No: MR-14R-384		Road Id No.:
Status of the Project:	Ongoing/Completed/Under gradation/Maintenance ✓	
Work is a case of:	New Connectivity/Up gradation/Maintenance ✓	
S.N.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3. Road Markings		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4. Compliance History		
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-


 18/11/20
 Signature

NAME: MTD. SHOAIB ALAM
 DESIGNATION: JE RWD. Ratna