

FIELD INSPECTION REPORT

Date of Inspection: 19/12/2020		District: Kishanganj	
Division: Kishanganj-1		Length(km): 0.65 km	
Name of the Road: Najorpur Shisabadi to Lohy			
Scheme/Programme: GTENY			
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed /Under Maintenance ✓	
Work is a case of:		New Connectivity/ Up gradation / Maintenance ✓	
S1. No	Parameters to be checked		Remarks
1.	Pavement		✓S/U
a)	Road Junction Condition		✓S/U
b)	Condition of Surfacing		S/U ✓
c)	Riding Quality		S/U
d)	Road Camber		✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓Yes/No
f)	Contraction Joints Provided or not (CC Pavement)		✓Yes/No
g)	Compaction of flank / shop & raincuts if any		Yes/No ✓
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting		S/SRI/U ✓
b)	Condition of Abutment & Wing walls, slab in RCC culverts		S/SRI/U
c)	Condition of railings/Slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No ✓
4.	Compliance History		
a)	Status of ATR's & any others		-

Overall Rating :

Satisfactory(S)	-
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	U

NAME: NIRMAL KUMAR

(Signature)  19/12/20