## FIELD INSPECTION REPORT

Dat	Date of Inspection: 19/12/11 District: Samastinur	71(1
_	D' ' DWD D 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
		abru
	Name of Road: Repairing werk keota approch or	ed PCC Nisman
	Scheme / Programme: MAINTENANCE	
	Package No: Old MR Road Id No: Bey	lood Maint
	Status of the Project: Ongoing/Completed/Under Maintenance	
	Work is a case of: New Connectivity/ Up gradation/ Maintenance	
SI. No	No Parameters to be Checked	Remarks
1	And the second s	
a)	a) Road Junction Condition	
b)	b) Condition of Surfacing	
c)	c) Riding Quality	
d)	d) Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	
f)	f) Construction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2	2 Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridge	
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4	4 Compliance History	
a)	a) Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	N/A
Satisfactory but requires Improvement(SRI)	11
Unsatisfactory(U)	

(Signature) XX

NAME: Despar Cl. Sinha DESIGNATION: J.C.