## FIELD INSPECTION REPORT

| Dat                         | e of Inspection: 191121 XX   | District: Samastipur   |            |  |
|-----------------------------|--|------------------------|------------|--|
| Division: RWD Dalsinghsarai |  | Length(km):            |            |  |
|                             | 27 1 0 1   | A 11                   | arthan     |  |
| Sch                         | eme / Programme: MAINTENANCE   | regar us (no) juring   | Miran)     |  |
| _                           | kage No: MR Old  | Road Id No: Regased    | AA - 1 4 1 |  |
| $\overline{}$               | us of the Project: Ongoing/Completed/Unde  | er Maintenance         | Maint.     |  |
|                             |  | gradation/ Maintenance |            |  |
| Sl.<br>No                   | Downwortows to be City 1 1   |                        | Remarks    |  |
| 1                           | Pavement   |                        |            |  |
| a)                          | Road Junction Condition  |                        |            |  |
| b)                          | Condition of Surfacing   |                        |            |  |
| c)                          | Riding Quality   |                        |            |  |
| d)                          | ) Road Camber  |                        |            |  |
| e)                          | Whether free from defects such as visible craggregates in case of CC Pavement  | racks, exposed         |            |  |
| f)                          | Constraction Joint provided or not(CC Pavement)  |                        |            |  |
| g)                          | Compaction of flank/slope & raincuts if any  Cross Drainage  |                        |            |  |
| 2                           |  |                        |            |  |
| a)                          | Condition of head walls in Hume pipe culve including its painting  | erts                   |            |  |
| b)                          | Condition of Abutment & Wing walls, Slab in RCC culverts   |                        |            |  |
| c)                          | Condition of railings/slab/approach for Bridge   |                        |            |  |
| 3                           | Road Furniture   |                        |            |  |
| a)                          | Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained |                        |            |  |
| 4                           | Compliance History   |                        |            |  |
| a)                          | Status of ATR's & any others   |                        |            |  |
|                             |  |                        |            |  |

## Overall Rating:

| Satisfactory(S)                            | N/A |  |
|--|-----|--|
| Satisfactory but requires Improvement(SRI) | 14  |  |
| Unsatisfactory(U)                          |     |  |

Alerka (Signature)

NAME: Deepar Ch. Sinha DESIGNATION: J.E