

FIELD INSPECTION REPORT		
Date of Inspection-	18-12-2020	District Patna
Division-	masaurhi	Length (KM) 3.2 KM
Name of Road-	Panpura to Baurhi	
Scheme/Programme-	Maintenance ✓	
Package no.-		Road Id No.
Status of the Project	On going/Complete/Under Maintenance ✓	
Work is a case of	New Connectivity/Up gradation/Maintenance ✓	
sl no.	Parameters to be Checked	Remarks
1	Pavement	✓
a	Road Junction Condition	S/U
b	Condition of Surfacing	S/U ✓
c	Riding Quantity	S/U ✓
d	Road Camber	S/U ✓
e	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No ✓
f	Contraction joints provided or not (CC Pavement)	Yes/No
g	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	✓
a	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b	Condition of Abutment & Wing walls, Slab in RCC Culverts	S/SRI/U
c	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	✓
a	Whether sign board/informatory/cautionary Board/KM & 200 m stones/Pavement road markings are provided and maintained	Yes/No ✓
4	Compliance History	
a	Status of ATR's & any others	-

Overall Rating:

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	✓

Note:- 1. Notice issued
2. work not started.

Name

Er. Yogeshwar Pandey
CE-2

Signature
C.E-2
18-12-20