## FIELD INSPECTION REPORT

Date of I	inspection:	19-12-2020	District: KATIHAA	
Division			MILLINA	
Name of the Road: Madi Paklant			Length (km): 9.33	
Scheme/Programme:		MAINTENANCE	to Ghoradika.	
	kage No.: Road Id No.: 21105600817			
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is	k is a case of:  New Connectivity/Up gradation/ Maintenance			
SI: No.		Parameters to	BUMERING ARBITATION OF A MARKET OF THE PROPERTY OF THE	Remarks
	Pavement			
a)	Road Junction	condition		·S/U_
b)	Condition of S	urfacing	i i	S/U
				~

Whether free from defects such as visible cracks, exposed

Condition of head walls in Hume pipe culverts including its painting

Whether sign boards/informatory/cautionary Board/km & 200m

Condition of Abutment & Wing walls, Slab in RCC culverts

stones/Pavement road markings are provided and maintained

## Overall Rating

c)

d)

e)

f)

g)

b)

c)

a)

a)

Riding Quality

Road Camber

aggregates in case of CC Pavement.

Cross Drainage

Road Furniture

Compliance History

Status of ATR's & any others

Contraction Joints provided or not (CC Pavement)

Compaction of flank/slope & raincuts if any

Condition of railings/slab/approach for Bridges

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRT
Unsatisfactory (U)	371

(Signature)

S/U

**√**S⁄/U

Yes/No

Yes/No

Yes/No

S/SRI/U

S/SRI/U

S/SRI/U

Yes/No

NAME:

Kamlesh chaudtary

**DESIGNATION:**