

FIELD INSPECTION REPORT

Date of Inspection: 19-12-2020		District: NAIAMBA	
Division: <i>Agri</i>		Length (km): 3.8 km	
Name of the Road: <i>Shankya Rasta Panjoli to Chakry</i>			
Scheme/Programme: MAINTENANCE		<i>for New maintenance 2018</i>	
Package No.:		Road ID No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		✓	
Work is a case of: New Connectivity/Up gradation/ Maintenance		✓	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U S	
b)	Condition of Surfacing	S/U S	
c)	Riding Quality	S/U S	
d)	Road Camber	S/U S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compection of flank/slope & raincuts if any	Yes/No/✓	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	✓ No
4.	Compliance History		
a)	Status of ATR's & any others	—	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

(Signature)
19/12/2020

NAME: *Rana Balwan Kumar Singh*
DESIGNATION: *Executive Engineer*

Scanned with CamScanner