

FIELD INSPECTION REPORT

Date of Inspection: 19.12.2020		District: NALANDA
Division: Raygir		Length (km): 2.00 Km
Name of the Road: Road from Katheringebur P.M. to V.K. to CRPF Camp		
Scheme/Programme: MAINTENANCE		MK-3054, New Maintenance Policy 2018
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No 4/
4.	Compliance History	
a)	Status of ATR's & any others	---

Overall Rating :

Satisfactory (S)	---
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	---

19.12.2020
(Signature)

NAME: Rana Basim Khatun Singh

DESIGNATION: Executive Engineer

Scanned with CamScanner