

# FIELD INSPECTION REPORT

Date of Inspection : 19/12/2020	District: Samastipur
Division : Patna	Length (km): 1.3
Name of the Road: Bahadur chak to Nandini Dhalg	
Scheme/Programme: MAINTENANCE	New maintenance
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance <u>Completed</u>
Work is a case of:	New Connectivity/Up gradation/ Maintenance <input checked="" type="checkbox"/>

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	U S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	X

Road furniture should be maintained.

Samir Kumar  
(Signature) 19/12/20

NAME: SAMIR KUMAR  
DESIGNATION: E-E