

FIELD INSPECTION REPORT

Date of Inspection :	19/12/2020	District:	Samastipur
Division :	Dalsing Sarai	Length (km):	2.28
Name of the Road:	MDR Rampur Jatalpur Path		
Scheme/Programme:	MAINTENANCE	New maintenance	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance <i>on going</i>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ☒		
SL No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	— S/U	
b)	Condition of Surfacing	— S/U	
c)	Riding Quality	— S/U	
d)	Road Camber	— S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	— Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	— Yes/No	
g)	Compaction of flank/slope & raincuts if any	— Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	— S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	— S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	— S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	— Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NA	

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	U

The completion period has expired. The contractor has not started the work. Action as per MBD clause against contractor has been directed.

Samir Kumar
(Signature) 19/12/2020

NAME: Samir Kumar

DESIGNATION: E.E