

FIELD INSPECTION REPORT

Date of Inspection : 19.12.2020		District: NALANDA	
Division : Bagair		Length (km): 3.8 Km	
Name of the Road: Repair of Amirgan RD Road to Barauli			
Scheme/Programme:		MAINTENANCE MR-3034	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance ✓	
Work is a case of:		New Connectivity/Up gradation/ Maintenance ✓	
SL No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U S	
b)	Condition of Surfacing	S/U U	
c)	Riding Quality	S/U U	
d)	Road Camber	S/U S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓	
4.	Compliance History		
a)	Status of ATR's & any others	—	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

19.12.2020
(Signature)

NAME: Rana Basim Kumar Singh
DESIGNATION: Executive Engineer

Scanned with CamScanner