

Old M/R

FIELD INSPECTION REPORT

old M/R 3054

Latitude: 25.559175
Longitude: 84.432519
Elevation: 57.54 m
Accuracy: 4.3 m
Time: 12-19-2020 14:22
Note: Osai Se Bela Path Ch 2.800

Date: 19/12/2020	District: Bhojpur
Location: 0-2 Jangalpur	Length (km): 2.8
Road: Repair of road from Osai to Bela	
Programme: MAINTENANCE	
Package No.:	Road Id No.: 101708067
Status of the Project: Ongoing/Completed/Under Maintenance	Under maintenance
Work is a case of: New Connectivity/Up gradation/ Maintenance	Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	N.A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Remarks: Pavements not painted. Appearance of a few patches.

Rectification done or not: Not
Rectification started or not: Not
Notice issued or not: Not

(Signature) Heer
19/12/20
EE

Powered by Note