## FIELD INSPECTION REPORT

Date of	Inspection: 1912.2020 District: Go algany				
Division: Go palgeny - 2. Length (km): 3.00 Km.					
Name of	the Road: Vishunburg to Pipra.				
Scheme	Programme: MAINTENANCE				
Package		and the same of th			
	f the Project: Ongoing/Completed/Under Maintenance	And the second s			
Work is	a case of: New Connectivity/Up gradation/ Maintenance	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1			
Sl. No.	Parameters to be checked	Remarks -			
1.	Pavement				
a)	Road Junction condition	S/U			
b)	Condition of Surfacing	S/U			
	Riding Quality	S/U			
c)	Road Camber	S/U			
d)	free from defects such as visible cracks, exposed	Yes/No			
e)	whether little Roman aggregates in case of CC Pavement.  Contraction Joints provided or not (CC Pavement)	Yes/No			
f)	Contraction Joints provided of not (CC 1 area)	Yes/No (			
g)	Compaction of flank/slope & raincuts if any Yes/No				
2.	Cross Drainage	S/SRI/JJ			
a)	Gardition of head walls in Hume pipe culverts including its painting	SISRUL			
The State of	Condition of Abutment & Wing walls, Slab in RCC culverts	Bisisio			
<u>b)</u>	Condition of railings/slab/approach for Bridges	S/SRI/U			
c)	Road Furniture				
3,	Road Furniture	Yes/No			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No			
4,	Compliance History				
a)	Status of ATR's & any others				

Overall Rating

Satisfacto	ry (S)		4 (CDI)		
Satisfacto	ry but requires	Improveme	nt (SK1)	· ·	
Timoticfor	The state of the s				CONTRACTOR OF THE PARTY OF THE

Dakesh Danjan Pandey. Executive Engineer. E: Yo LE-1.

(Signature)

NAME:

DESIGNATION: