

Latitude: 25.54483
 Longitude: 84.53189
 Elevation: 49.01 m
 Accuracy: 15.0 m
 Time: 12-19-2020 11:44
 Note: Bihiya Kateya Gumti se Ghagha Bajrangwali Chowk via Kunwardah path Ch 5.50 KM

M/R 3054

Date of Inspection: 19/12/20
 Division: R-6
 Name of the Road: Gumti to Ghagha Bajrangwali Chowk via Kunwardah
 Scheme/Programme: UNEP
 Package No.: 1040 170083
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance
 Road Id No.: 1040 170083
 Under maintenance
 Maintenance 3054

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	Nil
a)	Status of ATR's & any others	Nil

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Remarks: Appearance of a few patches & edge-breakages in the first km of the road. Sign boards (cautionary) were not found except one. Most of 200 M posts are missing.

NAME:

Rectification done or not: Not
 Rectification started or not: Not
 Notice issued or not: Not

(Signature)

19/12/20
 E E
 (N. A. ISHRAT)