

(41)

old M/R

FIELD INSPECTION REPORT

old m/r 3057

Date of Inspection :	19/12/2020	District:	Rohatpur
Division :	Road Jajpur	Length (km):	4.05 km
Name of the Road:	Sahyamb Lal to Rajwara		
Scheme/Programme:	MAINTENANCE		Maintenance
Package No.:		Road Id No.:	10/01708058
Status of the Project:	Ongoing/Completed/Under Maintenance		Under maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance		Maintenance
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U ✓	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓	
4.	Compliance History		
a)	Status of ATR's & any others	NIL	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	(SRI)
Unsatisfactory (U)	

Remarks: Appearance of pits, patches & edge breaking at some places. Road furniture's deficiency & apparently parapets not painted

NAME:

Rectification done or not: Not
 Rectification started or not: Not
 Notice issued or not: Yes

(Signature)

19/12/20
 EE

(N.A. ISHAPAT)