

Latitude: 25.609076
 Longitude: 84.51085
 Elevation: 64.91 m
 Accuracy: 6.4 m
 Time: 12-19-2020 12:50
 Note: NH-84 Amrai Nawada se Kalyanpur Baswanpur hote Belbaniyan CH 8.10KM

36 FIELD INSPECTION REPORT

Date of inspection : 19/12/2020		District: Bhojpur
Division : A.W-3 Jagdishpur		Length (km): 9.40 km
Name of the Road: NH-84 (Amrai Nawada) se Kalyanpur Baswanpur hote Belbaniyan		
Scheme/Programme: MAINTENANCE		Package No.: 3057
Package No.:		Road Id No.: 10401708060
Status of the Project:	Ongoing/Completed/Under Maintenance Under maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	N/D

Overall Rating :

Satisfactory (S)	SRI
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Remarks: 200 M posts & cautionary board not found
 Parapets not repaired & painted

(Signature) 19/12/20

E.E.

(N.A. ISHRAT)

NAME:

Rectification done or not: Not
 Rectification started or not: Not
 Notice issued or not: Not