

37

CID M/R

FIELD INSPECTION REPORT

Date of Inspection : 19/12/2020	District: Bhojpur
Division : R.W.D Jagadishpur	Length (km): 6.00 km
Name of the Road: PWD Road se Jamnaka Baruna Dalpatpur Note Hade Hade	
Scheme/Programme: MAINTENANCE	old M/R 3054
Package No.:	Road Id No.: 10401708063
Status of the Project: Ongoing/Completed/Under Maintenance	under maintenance
Work is a case of: New Connectivity/Up gradation/ Maintenance	maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N-A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	Nil

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	(SRI)
Unsatisfactory (U)	

Remarks: Exposed aggregates in CC pavement found at some places.
It needs rectification. Cautionary boards not found.

NAME:

Rectification done or not : Not
Rectification started or not : YES
Notice issued or not : Not

(Signature)

19/12/20
E.E.
(N.A. ISHARAT)