

39 40

Old M/R

FIELD INSPECTION REPORT

Date of Inspection :	19/12/2020	District:	Bhojpur
Division :	Road Transport	Length (km):	4.00 km
Name of the Road:	NH-24, Rura, Bihar, Sec. p.w. more Bhojpur		
Scheme/Programme:	MAINTENANCE	old maintenance 3054	
Package No.:		Road Id No.:	10401708065
Status of the Project:	Ongoing/Completed/Under Maintenance	Under maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U ✓	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓	
4.	Compliance History		
a)	Status of ATR's & any others	N/A	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	(SRI)
Unsatisfactory (U)	

Remarks : B.T. surface damaged at some places.

Rectification done or not: Not

Rectification started or not: Not

Notice issued or not: yes.

NAME:

(Signature) EE

(N.A. ISHRAAT)