

FIELD INSPECTION REPORT

| Date of Inspection : 18.12.2020 | | District : Bhagalpur |
|--|--|--------------------------|
| Division : Bhagalpur | | Length (km) : 2.00 |
| Name of Road : Yogiveer to Kola Khurd | | |
| Scheme/Programme : New Maintenance Policy 2018 | | |
| Package No. : 03 | | Road Id No.: 20703201040 |
| Status of the Project : Ongoing | | |
| Work is a case of : Up gradation | | |
| Sl. No. | Parameters to be checked | Remarks |
| 1 | Pavement | |
| a) | Road Junction condition | NA |
| b) | Condition of Surfacing | NA |
| c) | Riding Quality | NA |
| d) | Road Camber | NA |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | NA |
| f) | Contraction Joints provided or not (CC Pavement) | NA |
| g) | Compaction of flank/slope & raincuts if any | NA |
| 2 | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | NA |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | NA |
| c) | Condition of railings/slab/approach for Bridges | NA |
| 3 | Road Furniture | |
| a) | Whether sign board /informatory/cautionary Board/km & 200m stones/Pavement Road marking are provided and Maintained | Yes |
| 4 | Compliance History | |
| a) | Status of ATR's & any others : Work has not been started as yet. | |

| | | |
|------------------|---|----|
| Overall Rating : | Satisfactory (S) | NA |
| | Satisfactory but requires Improvement (SRI) | |
| | Unsatisfactory (U) | |

NAME : KUMAR RAKESH

DESIGNATION : EXECUTIVE ENGINEER

(Signature)

[Signature]
18-12-2020