

FIELD INSPECTION REPORT

Date of Inspection : 16-12-2020	District: Muzaffarpur
Division : Muzaffarpur East-1	Length (km): 1.20 KM
Name of the Road: NH-77 Sakri chawk to Sakri Saraiya (Muslim Tola)	
Scheme/Programme: MAINTENANCE	NHGSY (Gen)
Package No.:	Road Id No.: 31507212063
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Some 200m post missing Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N-A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
☒ Unsatisfactory (U)	U

Road Surface damaged due to heavy rain and flood

NAME:

Bijendra Kumar
16/12/2020

DESIGNATION:

JE/RWD(W)
Kutani

K Anilish
16/12/20
(Signature)

AE

RWD (W)

Kutani