

FIELD INSPECTION REPORT

Date of Inspection :	District: <u>Muzaffarpur</u>	
Division : <u>Muzaffarpur East - 01</u>	Length (km): <u>1.910 KM</u>	
Name of the Road: <u>Titara haat Lohi Se Vidyashah thaliya Siman Via</u>	Road Id No.: <u>31507212066</u>	
Scheme/Programme: <u>MAINTENANCE</u>	Remarks: <u>Ram Tola UCO Bank</u>	
Package No.:	Status of the Project: <u>Ongoing/Completed/Under Maintenance</u>	
Work is a case of:	<u>New Connectivity/Up gradation/ Maintenance</u>	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	<u>U</u>

Shrawan
19.12.2020
re

(Signature)

NAME:

DESIGNATION: