

# FIELD INSPECTION REPORT

|                        |                                               |              |            |
|------------------------|-----------------------------------------------|--------------|------------|
| Date of Inspection :   | 12/12/2020                                    | District:    | MVZ.       |
| Division :             | Coradga R.W.D MVZ                             | Length (km): | 1.5 km     |
| Name of the Road:      | Turki Road chauranipul to Bahilwara panchayat |              |            |
| Scheme/Programme:      | MAINTENANCE                                   | Road Id No.: | mmmsy (SC) |
| Package No.:           |                                               |              |            |
| Status of the Project: | Ongoing/Completed/Under Maintenance           |              |            |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance    |              |            |

| Sl. No. | Parameters to be checked                                                                                             | Remarks   |
|---------|----------------------------------------------------------------------------------------------------------------------|-----------|
| 1.      | Pavement                                                                                                             |           |
| a)      | Road Junction condition                                                                                              | ✓ S/U     |
| b)      | Condition of Surfacing                                                                                               | S/U ✓     |
| c)      | Riding Quality                                                                                                       | ✓ S/U     |
| d)      | Road Camber                                                                                                          | ✓ S/U     |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | ✓ Yes/No  |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | ✓ Yes/No  |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | ✓ Yes/No  |
| 2.      | Cross Drainage                                                                                                       |           |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI ✓   |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | ✓ S/SRI/U |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | ✓ S/SRI/U |
| 3.      | Road Furniture                                                                                                       |           |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No  |
| 4.      | Compliance History                                                                                                   |           |
| a)      | Status of ATR's & any others                                                                                         |           |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | ✓ |
| Satisfactory but requires Improvement (SRI) | ✓ |
| Unsatisfactory (U)                          | U |

*Anil Kumar*  
12/12/2020  
(Signature)

NAME:

DESIGNATION: