

FIELD INSPECTION REPORT

Date of Inspection:	18/12/2020	District:	Darbhanga
Division:	Darbhanga-1	Length(Km):	2.40
Name of Road:	Kulwara to purnanola		
Scheme/Programme:	Maintenance		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/.Maintenance		
S No.	Parameters to be Checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U U	
b)	Condition of Surfacing	S/U U	
c)	Riding Quality	S/U S	
d)	Road Camber	S/U S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	No Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes	
g)	Compaction of flank /slope & raincuts if any	Yes/No No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	N/A S/SRI/U	
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts	N/A S/SRI/U	
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U N/A	
3	Road Furniture		
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and-maintained	Yes Yes/No	
3	Compliance History		
a)	Status of ATR's & any others	Yes	
Overall Rating:			
Satisfactory (S)			
Satisfactory but requires Improvement (SRI)			
Unsatisfactory (U)		U	

Road is damaged at few points due to current year and previous year flood

(Signature)

Name:

Designation:

18/12/2020
S.E.