FIELD INSPECTION REPORT

Date of	f Inspection :	18:12:2021	District: Madhybani		
Division: Jay oray qx			Length (km): 4.463km	Length (km): 4.463km Dunga Asthan to Paroriyahi Hotohye KA	
Name (of the Road: C	reijikam Barki	tol Dunga Asthan to Paroriyahi	Hotolye Ko	ytan
otheme	ar rogramme:	MAINTENAL	NCE .		
Package No.: nm 155y (Gen)			Road Id No.:		
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance			
201-1-100-1-100	Augustial entries and and and an augustial and an augustial and an augustial and augustial augus	CONTRACTOR OF THE PROPERTY OF THE PARTY OF T	vity/Up gradation/ Maintenance		4
SI. No.		Paramete	ers to be checked	Remarks	
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainag	e in a			
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			Š/SRI/U	
-/	Condition of railings/slab/approach for Bridges			S/SRI/U	MI
3.	Road Furniture				
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No				
	edingliante il	die.		an and a supplication of the	
i) S	Status of ATR's & any others				

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SR1
Unsatisfactory (U)	

(Signature)

NAME: Sahdenehunghary

DESIGNATION: J. E