FIELD INSPECTION REPORT

GTSNA

Date of Inspection: 16/12/2020 District: Janus					ar and a second
Division: Length (km): 1.20 Km					
Name o	of the Road:	Lairo March' K MAINTENANCE	le Ghaz Se Badron	ut PM454	wa Kapiya
		MAINTENANCE		Path	00
Package No.: Road Id No.: 2080 41					
Status of the Project: Ongoing/Completed/U					
		DESCRIPTION OF THE PROPERTY OF	//Up gradation/ Maintenance		
SI No.	College Colleg			Remarks	
	Pavement				
a)	Road Junction condition			SAU	
b)	Condition of Surfacing			SÆ	
c)	Riding Quality			SAU	
d)	Road Camber			SÆ	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/ No	
g)	Compaction of flank/slope & raincuts if any			Yes/ No	
	ed to a transfer of the second second				
a)	Condition of head walls in Hume pipe culverts including its painting			S/ SRI/ U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/ SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/ SRI/U	
	Rosu-cumiture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			-Yes /No	
李州	Compliance distort was the second				
a)	Status of ATR's & any others N/A				

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

NAME:

DESIGNATION:

(Signature)