FIELD INSPECTION REPORT

Date of	Inspection:	16/12/2020	District: Tamen'	
Division	· va	mui'	Length (km): 1.50 K	
	f the Road:	boole Muda	1.301/19	.7_
	Programme:	MAINTENANCE	Tally Tally	
Package	A REAL PROPERTY AND ADDRESS OF THE PARTY AND A		Road Id No.: 20804118	D17
Status of the Project: Work is a case of:		Ongoing Completed Under Maintenance		
and the state of	The state of the s	New Connectivity/I	Jp gradation/ Maintenance	
SI/No.	San State of San		de checked	Remarko
1.	Pavement			de Klassian
a)	Road Junction condition			SÆ
b)	Condition of Surfacing			SÆ
c)	Riding Quality			SÆ
d)	Road Camber			SÆ
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/ No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			_Yes/No
跨 测量	election directors are a second as a second			SECUL PROPERTY.
a)	Condition of head walls in Hume pipe culverts including its painting			-S/SRIAU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			_Yee/No
	edomoli ide	iorvey Paris	THE STATE OF THE S	
a)	Status of ATR's & any others			NA

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Ship 20

(Signature)

NAME:

DESIGNATION: